

**Nu-Metrics Traffic Analyzer Study
Computer Generated Summary Report**

City: Stettler

Street: 68 St.

Location: North of 41 Ave.

A study of vehicle traffic was conducted with HI-STAR unit number 0001. The study was done in the Northbound lane at 68 St. in Stettler, AB in Stettler county. The study began on Jul/28/11 at 14:34 and concluded on Aug/08/11 at 14:04, lasting a total of 263.50 hours. Traffic statistics were recorded in 60 minute time periods. The total recorded volume showed 3436 vehicles passed through the location with a peak volume of 37 on Aug/06/11 at [10:34-11:34] and a minimum volume of 0 on Aug/05/11 at [23:34-00:34]. The AADT count for this study was 313.

SPEED

Chart 1 lists the values of the speed bins and the total traffic volume for each bin. At least half the vehicles were traveling in the 48 - 56 KM/H range or lower. The average speed for all classified vehicles was 51 KM/H with 66.07% vehicles exceeding the posted speed of 50 KM/H. The HI-STAR found 0.00 percent of the total vehicles were traveling in excess of 89 KM/H. The mode speed for this traffic study was 48KM/H and the 85th percentile was 61.55 KM/H.

<	16	24	32	40	48	56	64	72	80	89	97	105	113	121				
to	to	to	to	to	to	to	to	to	to	to	to	to	to	to				
15	23	31	39	47	55	63	71	79	88	96	104	112	120	>				
21	11	62	303	769	1273	693	251	44	6	3	0	0	0	0				

CHART 1

CLASSIFICATION

Chart 2 lists the values of the classification bins and the total traffic volume accumulated for each bin .

Most of the vehicles classified during the study were Tractor Trailers. The number of Passenger Vehicles in the study was 1248 which represents 36 percent of the total classified vehicles. The number of Vans & Pickups in the study was 0 which represents 0 percent of the total classified vehicles. The number of Busses & Trucks in the study was 0 which represents 0 percent of the total classified vehicles. The number of Tractor Trailers in the study was 2188 which represents 64 percent of the total classified vehicles.

<	1.9	2.2	2.3	2.4	2.5	2.6	2.8	3.0	3.1	3.2	3.4	3.7	4.2	4.3				
to	to	to	to	to	to	to	to	to	to	to	to	to	to	to				
1.8	2.1	2.2	2.3	2.4	2.5	2.7	2.9	3.0	3.1	3.3	3.6	4.1	4.2	>				
59	0	16	0	11	0	24	0	58	0	0	165	219	696	2188				

CHART 2

HEADWAY

During the peak traffic period, on Aug/06/11 at [10:34-11:34] the average headway between vehicles was 94.737 seconds. During the slowest traffic period, on Aug/05/11 at [23:34-00:34] the average headway between vehicles was 3600 seconds.

WEATHER

The roadway surface temperature over the period of the study varied between 0.00 and 0.00 degrees C. The HI-STAR determined that the roadway surface was Dry 100.00% of the time.